



BAVARIAN AUTOSPORT

Business C/D Radio Update Instructions

SITUATION: Some DC43DIN/C43DIN radios default to 4 digit European security code. Not all USA stations will be received if the tuner is left in the European mode.

CAUSE: Default setting in the radio is set to European mode (4 digit code).

CORRECTION: Enter the 4 digit code, then enter into the service mode and switch to the USA tuner. If the radio displays the space for the 5 digit code, then the tuner is already in USA mode.

3 Series

96 thru 98

PARTS LIST:

65 12 6 909 884

BMW Business C/D Radio

3 Series

Convertibles

96 thru 99

PROCEDURE:

C43DIN (cassette):

1. Turn key to "ON" position.
2. Turn radio "ON", then turn "OFF" and then "ON".
3. Press and hold the "M" button for approximately 10 seconds. Display will show "SN#".
4. You are now in the "Service Mode".
5. Use the "-" and "+" keys to scroll through various functions until "Tuner Area" is selected. The display will read "Europe".
6. Use the "<" or ">" keys to select "USA".
7. Turn radio "OFF" to set changes.

M3

96 thru 99

Z3

All

CD43DIN (compact disc):

1. Turn key to "ON" position.
2. Turn radio "ON", then turn "OFF" and then "ON".
3. Press and hold the "M" button for approximately 10 seconds. Display will show "SN#".
4. You are now in the "Service Mode".
5. Use the "-" and "+" keys to scroll through various functions until "Tuner Area" is selected. The display will read "Europe".
6. Use the "1" or "6" keys to select "USA".
7. Turn radio "OFF" to set changes.



Call Toll Free: **1.800.535.2002**